




Vedení táhla  $\phi 6$ 




X	Y	Kat.č
11,5	8	03.341
22,5	27	03.342

Příklad objednávky: Vedení táhla 6/03.340

Vedení táhla  $\phi 8$ 

## Vedení táhla 3x14

Kat.č. 03.031



Kat.č.	A (mm)	L (mm)	h (mm)
03.029	20	33	24
03.030	26	39	30
03.475	32	45	36

Příklad objednávky: Vedení táhla 8/03.029

Příklad objednávky: Vedení táhla 3x14/03.031